

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville, Tennessee 37243

Tennessee Multi-Sector General NPDES Permit (TMSP) Compliance Inspection Report NPDES Tracking Facility Name: Number: TNR John Sevier Hu Street Address: County: Facility SIC Effective Date: TMSP Sector(s): Code(s): Time of Exit: Inspection Date: Time of Entry: Notice of Coverage (NOC) and Stormwater Pollution Prevention Plan (SWPPP) Yes 0 Is the facility's NOC retained on-site or available upon request? Ø Has the facility developed and maintained a SWPPP? Does the SWPPP include; a detailed site map identifying drainage, outfalls, pollutant potential areas and BMPs W/ Tallet o' an inventory of potential pollutant sources? Table 1-1 Ø a pollution prevention team? Q/ a list of measures and controls to prevent pollution? a description of good house keeping practices? a list of erosion prevention and sediment controls? ď a list of significant spills and leaks of toxic and hazardous pollutants? g W a description of spill prevention and response procedures? 1 a certification page signed by the appropriate authority? a description of employee training and dates delivered? a certification of testing for presence of non-storm-water discharge? ď NA Quarterly Visual Examination of Stormwater Quality Yes Has the permittee performed quarterly visual examinations in accordance with the requirements of the TMSP? Are the visual examination reports retained on-site or available upon request? Yes Stormwater Monitoring Has the permittee performed stormwater monitoring at all of the outfalls? 2015 Have all of the required parameters been monitored? Have the samples been collected in accordance with the requirements of the TMSP and/or 40 CFR? 4 Are the monitoring reports and associated documentation retained on-site or available upon request? Q-1 Did the facility notify the Division within the required time frame if benchmark exceedances occurred? U/ NA Yes Comprehensive Site Compliance Evaluations and Inspections Has the permittee performed annual comprehensive site compliance evaluations? Has the permittee performed any required site inspections? Are the evaluations and inspection records retained on-site or available upon request? No N/A Facility BMP Review Are the site BMPs in accordance with the SWPPP? Have the BMPs been installed correctly and maintained? Have good housekeeping measures been implemented and maintained?

Outfall and Receiving Waters (where applicable)	001	Outfall # 00 0-	Outfall # 005
Was an outfall discharging at time of inspection? If yes, expl	ain		
observations (source/color/odor/foam/scum/solids etc.).			
Condition of receiving water upstream from the outfall?			
Condition of receiving water feet downstream of the o	utfall?		
Condition of receiving water feet downstream of the o	utfall?		

Observations and Comments:

frached anto the yard located so it can contact Site. Short dirtace to	has blown is of (South Yard) t story vater discharge posh	Perhaps been 1 to 1 t
	AQUA CHEM Global. Water. Solutions.	Tracy Gamble Facilities Supervisor tgamble@aqua-chem.com 3001 E. Gov. John Sevier Hwy Knoxville, TN 37914 www.aqua-chem.com o: 865-549-5428 f: 865-546-4330 c: 865-851-0990

On-Site Contact Person:	DWR Inspector:
Print Name: TURCY Gamble Title: Aqua-enen Date: 4-27-16	Print Name: Allen Wolkinson Title: Engineer Date:
Signature: Over 200	Signature: Allen Williams
Phone: 865 - 549 - 5428	Phone: 865-594-5588
Email: +gomble @ ogva-chem: com	Email: allen. Wilkinson Gtn.gov

Soft W